



A diagram illustrating a safety hazard. On the left, a mechanical component, possibly a door hinge or latch, is shown. To its left is a triangular warning symbol containing an exclamation mark. To the right of the mechanical part is a silhouette of a person's head. A large 'X' is drawn over the area between the mechanical part and the person's head, indicating a potential point of contact or a hazard zone.

7

1.



2.




click

click





Kinvaro S-35



3






4




5




6








2.




3.




4.



7



8



G*GRASS®

Hetal-Werke
 Franz Hettich GmbH & Co. KG
 P.O.Box 1240
 D-72272 Alpirsbach
 Germany
 Phone +49 / 7444 / 68-0
 Fax +49 / 7444 / 68-110
 info@grass.eu
 www.grass.eu