


H60 F



x1



x2



x2




x1



x1



x1





x1




60
KG

1





2x




1

2





2

$$L_{\min} = 2L_0 + 100\text{mm}$$




3




L [mm]	1200	1400	1500	1600	1800	1940	2000	2400	3000
n	4	5	5	6	6	7	7	8	10


4





5






6






7






8



9



10



OPTIONS / OPTIONEN / OPTIONS / OPCIONES / OPCJE

